School Name : Voorheesville High School								
Lab ELAP id#: 10478 Primary Accrediting Body					Method of Analysis: EPA 200.8			
Lab ID #	School Sample ID	Collection Date	Sample Location	Outlet Description	Initial/Post Remediation	Lead Result ug/L (PPB)	Lab Report Receipt Date	Action Taken
70287670001	VHS - 1	2/16/2024	Gym Hall by Mud room	Drinking Fountain	Initial	6.2	2/22/24	Repalced with new bottle filler
70287670002	VHS – 2	2/16/2024	Hall by Coach Office	Drinking Fountain	Initial	<1.0	2/22/24	
70287670003	VHS – 2A	2/16/2024	Hall by Coach Office	Bottle Filler	Initial	<1.0	2/22/24	
70287670004	VHS – 3	2/16/2024	Hall by Weight room	Drinking Fountain	Initial	<1.0	2/22/24	
70287670005	VHS – 4	2/16/2024	Kitchen	Ice Machine	Initial	<1.0	2/22/24	
70287670006	VHS – 5	2/16/2024	Kitchen	Prep Sink	Initial	1.1	2/22/24	
70287670007	VHS – 6	2/16/2024	Hall by Commons	Drinking Fountain	Initial	<1.0	2/22/24	
70287670008	VHS – 6A	2/16/2024	Hall by Commons	Bottle Filler	Initial	<1.0	2/22/24	
70287670009	VHS – 7	2/16/2024	Faculty Room 133	Sink	Initial	2.8	2/22/24	
70287670010	VHS – 8	2/16/2024	Hall by 131	Drinking Fountain	Initial	3.8	2/22/24	
70287670011	VHS – 8A	2/16/2024	Hall by 131	Bottle Filler	Initial	4.2	2/22/24	
70287670012	VHS – 9	2/16/2024	Hall by 120	Drinking Fountain	Initial	<1.0	2/22/24	
70287670013	VHS – 9A	2/16/2024	Hall by 120	Bottle Filler	Initial	<1.0	2/22/24	
70287670014	VHS – 10	2/16/2024	Nurses Office	Sink	Initial	2	2/22/24	
70287670015	VHS -10A	2/16/2024	Nurses Office	Bathroom Sink	Initial	4.6	2/22/24	
70287670016	VHS – 11	2/16/2024	Hall by HS Office	Drinking Fountain	Initial	<1.0	2/22/24	
70287670017	VHS – 11A	2/16/2024	Hall by HS Office	Bottle Filler	Initial	<1.0	2/22/24	